

THIS UPDATE IS ONLY REQUIRED IF YOUR BASEBAND IS NOT ON SCT3258 VER V2.01.07BA
THIS UPDATE WILL REPAIR APRS AND SMS ISSUES ON OLDER BASEBAND RADIOS

1. Hold pressing # key and orange/blue top key, at the same time power on the radio, screen display



“WARNING This is Boot Mode for Sct!!!”



2. Use the USB cable to connect radio and your PC





3. Run the SetupSCT_PORT.msi and install.


4. Run SCT_PORT.exe






Choose the correct com port







Open the .hex file



Click on “Init Port” to check the com port connection is correct



Click on "Flash Update" to start the SCT update



The update is done.